

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

317  
ESE  
1/4-1/2  
0.487 mi.  
2573 ft.

**SERVICE BOX 4595  
ES OF BRIGHTON & 3RD ST  
BROOKLYN, NY**

**NY Spills S106126685  
N/A**

**Relative:  
Higher**

**Actual:  
8 ft.**

**SPILLS:**

Name: SERVICE BOX 4595  
Address: ES OF BRIGHTON & 3RD ST  
City,State,Zip: BROOKLYN, NY

Spill Number/Closed Date: 0309035 / 2005-06-29

Facility ID: 0309035

Facility Type: ER

DER Facility ID: 83961

Site ID: 93673

DEC Region: 2

Spill Cause: Unknown

Spill Class: C4

SWIS: 2401

Spill Date: 2003-11-24

Investigator: JHOCONNE

Referred To: Not reported

Reported to Dept: 2003-11-25

CID: 255

Water Affected: Not reported

Spill Source: Unknown

Spill Notifier: Affected Persons

Cleanup Ceased: Not reported

Cleanup Meets Std: False

Last Inspection: Not reported

Recommended Penalty: False

UST Trust: False

Remediation Phase: 0

Date Entered In Computer: 2003-11-25

Spill Record Last Update: 2005-06-29

Spiller Name: Not reported

Spiller Company: UNKNOWN

Spiller Address: SAME

Spiller Company: 001

Contact Name: PAUL DIDONATO

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL e2mis no. 151-258: 11/24/03=1130HRS DEROSA WHILE DOING INSPECTION IN VS-4595 FEEDER 11B02 FOUND APPROX 1-GALLON OF UNKNOWN OIL ON APPROX 200 GALLONS OF WATER. IT APPEARS TO BE CONTAINED AT THIS TIME NO SEWER OR WATERWAYS AFFECTED. UNIT WAS PRESSURE TESTED AND HELD OK (OIL LEVEL GOOD). SAMPLE TAKEN. UPDATE 11-24-03 21:00HRS LAB SEQ# 03-09502-00 <1.0 PPM. UPDATE 11-25-0 0:30HRS THIS JOB WILL BE TAKEN OFF THE 24HR CLOCK BECAUSE OF SCAFFOLDING NEAR STRUCTURE. 1/26/04 23:15 HRS. -- D. LICHTENSTEIN OF BROOKLYN ENV. OPS. REPORTS THAT HE & S.ROSENKING REMOVED ALL LIQUIDS AND SOLIDS WITH VACTOR, DOUBLE WASHED STRUCTURE WITH BIOGEN 760, FOUND SUMP ALREADY SEALED AND REMOVED ENV. STOP TAG #11453. CLEANUP COMPLETE AT THIS TIME."

Remarks: "1 gallon on 200 gallons of water - coming off 24 list - cleaning pending scaffolding removal. Con Ed #151258"

**All Materials:**

Site ID: 93673

Operable Unit ID: 875133

Operable Unit: 01

Material ID: 498950

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 1.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported